

## FITNESS CERTIFICATE

( To be filled by inspecting officer )

(Re: G.O.Ms.20/70/PWD Dt. 23-01-1970)

- 1 Name of the Officer : ABHA.V.S.  
2 Name of the school : SANTA CRUZ PUBLIC SCHOOL  
3 Location with name : Eramallor  
of educational district/ : Cherthala  
sub district : Thuravoor  
4 Classification of building : R.C.C.Multi storied building  
as specified in column  
no.4 in application for  
fitnesscertificate and size :

GF	FF	SF
Class room-9nos 22'X20'	Class room-10nos. 22'X20'	Science lab-1no.79'X20'
Class room HSS -2nos 33'X20'	Classroom HSS -4 nos. 33'X20'	Chemistry lab-1no.45'X20'
Office -1nos 22'X20'	Computer room-1no.22'X20'	Physics lab-1no.56'X20'
Staff room-1no 45'X20'	Prayer room-1no.45'X20'	Math's lab-1no.33'X20'
Lobby -1 no 22'X20'	Library and	Audio visual
Manager room-1no22'X20'	Reading room-1no.33'X20'	Room-1no.68'X20'
principal'sroom-1no17'X20'	Store room1no. 11'X20'	Art Edn.room--1no.33'X20'
Jr.principal'sroom-1no17'X20'	Stair room3nos 11'X20'	Classroom HSS -2 nos. 33'X20'
<b>Toilet Block</b>	<b>Toilet Block</b>	Store room-5nos. 11'X20'
Girls-1no. 11'X20'	Girls-1no. 11'X20'	<b>Toilet Block</b>
Boys-1no. 11'X20'	Boys-1no. 11'X20'	Girls-1no. 11'X20'
Stair room-3nos11'X20'		Boys-1no. 11'X20'
sick room 1no.22'X20'		Stair room-3nos11'X20'
Store room1no. 11'X20'		

- 5 Period for which certificate is issued : 01/06/2023 to 31/05/2024

- 6 NATURE OF DEFECT IF ANY :
- a)Foundation&basement : NIL  
b)Super structure : NIL  
c)Doors and windows : NIL  
d)Wood work wrought and put up : NIL  
e)Roof : NIL  
f)Flooring : NIL  
g)Miscellaneous(Cracks etc) : NIL

- 7 Any major defects noticed which will render the building un safe in any matter : NO

P.T.O.

8 Whether maintenance works have been done properly : YES

9 Whether the structure is sound or not for conducting classes : Yes ,the structure is safe under normal weathering conditions.


1.The stability of the structure should be examined also with reference to location, altitude,intensity of wind exposure to flood etc.

2.Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified the the school was inspected by me on 27/05/2023 and found to be fit to conduct classes for a period from 01/06/2023 to 31/05/2024 as per the reasons stated above.

Place : Eramalloor  
Date : 27/05/2023



  
Assistant Engineer  
LSGD Section  
Ezhupunna  
Assistant Engineer  
LID & EW Section  
Ezhupunna Grama Panchavath