

FITNESS CERTIFICATE

(To be filled by inspecting officer)

(Re: G.O.Ms.20/70/PWD Dt. 23-01-1970)

- 1 Name of the Officer, : DEEPTHI JAMES
 2 Name of the school : SANTA CRUZ PUBLIC SCHOOL
 3 Location with name of educational district/ sub district : Eramallor Cherthala : Thuravoor
 4 Classification of building as specified in column no 4 in application for fitness certificate and size : R.C.C.Multi storied building

GF	FF	SF
Class room-9nos 22'X20'	Class room-10nos. 22'X20'	Science lab-1no.79'X20'
Class room HSS -2nos 33'X20'	Classroom HSS -4 nos. 33'X20'	Chemistry lab-1no.45'X20'
Office -1nos 22'X20'	Computer room-1no.22'X20'	Physics lab-1no.56'X20'
Staff room-1no 45'X20'	Prayer room-1no.45'X20'	Math's lab-1no.33'X20'
Lobby -1 no 22'X20'	Library and	Audio visual
Manager room-1no22'X20'	Reading room-1no.33'X20'	Room-1no.68'X20'
principal's room-1no17'X20'	Store room1no. 11'X20'	Art Edn. room--1no.33'X20'
Jr.principal's room-1no17'X20'	Stair room3nos 11'X20'	Classroom HSS -2 nos. 33'X20'
Toilet Block	Toilet Block	Store room-5nos. 11'X20'
Girls 1no. 11'X20'	Girls-1no. 11'X20'	Toilet Block
Boys-1no. 11'X20'	Boys-1no. 11'X20'	Girls-1no. 11'X20'
Stair room-3nos11'X20'		Boys-1no. 11'X20'
sick room 1no.22'X20'		Stair room-3nos11'X20'
Store room1no. 11'X20'		

- 5 Period for which certificate is issued : 01/06/2021 to 31/05/2022
- 6 NATURE OF DEFECT IF ANY :
- a) Foundation & basement : NIL
 b) Super structure : NIL
 c) Doors and windows : NIL
 d) Wood work wrought and put up : NIL
 e) Roof : NIL
 f) Flooring : NIL
 g) Miscellaneous (Cracks etc) : NIL

- 7 Any major defects noticed which will render the building unsafe in any matter : NO

P.T.O.

8 Whether maintenance works have been done properly : YES

9 Whether the structure is sound or not for conducting classes : Yes, the structure is safe under normal weathering conditions.

1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure to flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 26/05/2021 and found to be fit to conduct classes for a period from 01/06/2021 to 31/05/2022 as per the reasons stated above.

Place : Eramalloor
Date : 26/05/2021



Deepthi
Assistant Engineer
LSGD Section
Ezhupuzha
Assistant Engineer
L.S.G.D Section, Ezhupuzha
Ezhupuzha Grama Panchayath